

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**CW498**  
**East**  
**1/2-1**  
**0.772 mi.**  
**4076 ft.**

**BASEMENT**  
**315 OCEAN VEIW AVE**  
**BROOKLYN, NY**

**Site 1 of 2 in cluster CW**

**NY Spills** **S111318369**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**9 ft.**

**SPILLS:**

Name: BASEMENT  
Address: 315 OCEAN VEIW AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1109487 / 2011-10-31  
Facility ID: 1109487  
Facility Type: ER  
DER Facility ID: 411746  
Site ID: 457263  
DEC Region: 2  
Spill Cause: Human Error  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2011-10-29  
Investigator: SFRAHMAN  
Referred To: Not reported  
Reported to Dept: 2011-10-29  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Private Dwelling  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2011-10-29  
Spill Record Last Update: 2011-10-31  
Spiller Name: CALLER  
Spiller Company: UNKNOWN  
Spiller Address: 315 OCEAN VEIW AVE  
Spiller Company: 999  
Contact Name: CALLER  
DEC Memo: "Spoke with BOB. He told me that the fill line was not connected to a tank. Driver stopped the pumps he did not hear any whistle. Approx 10 gallon spilled onto the basement floor. There was no drain or cracks on the floor. Driver put down speedy dry on the floor. Atlantic Response was retained to complete the clean up. Later on I spoke with the Atlantic Response Supervisor and he told me that clean up was completed with speedy dry and absorbent pad. He also told me that there was no drain on the floor. There was minor oil in the sump pit and he cleaned it up with absorbent.(sr) \*\* I spoke with House owner Mia Parlakky(646-415-3472), she said the clean up was good.No odor in the house.Case closed.\*\*\*"  
Remarks: "Cut line by accident. Spill is contained. Atlantic response enroute to clean up."

**All Materials:**

Site ID: 457263  
Operable Unit ID: 1207389  
Operable Unit: 01  
Material ID: 2204663  
Material Code: 0001A

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported